


PROPELLER RUN HRS ADJUSTMENT

1. New Sub-menu added:



2. On selecting above, enter Aircraft Regn

CAFAM System

A/cft	C-GABC	A/P Cat	RVSM?
Type		Owner	
Serial		Unit	
		YrManf	

3. Screen now displays

A/cft	C-GABC	A/P Cat	1	RVSM?	S	Hrs New	1254.9	Current at	
Type	DA40-D	Owner	BANAVIA			Landing	1174	15/12/2010	
Serial	D4-225	Unit				Cycles	0	Fatg.tm	0
		YrManf	2006						

Adjustments to Propeller Hrs/Cyc following Maintenance (Ground Runs etc)

Type	MTV-6-A/187-129	Total Time	Total Cycs
S/No1	061183	854.4	0
S/No2		0.0	0
S/No3		0.0	0
S/No4		0.0	0

S/No Adjustment to Hrs Cycs

Position of Propeller Components FROM TO

OK Cancel

4. Select S/no, adjustment hrs and Range of Components if applicable to update the adjustment times