

REQUISITIONS

Zenner (Evaluation)
CAFAM64 System-Main Menu

Network:Y
JD- 07/05/2013

CAFAM64

Job No 049254/HA Item10002 24/05/2012 Est. Man-hrs 0.00 Trade
X-Ref Cust Approvd Y
Descr Refit replacement LH Fuel Boost pump P/no F123-1
ATA following above removal
Rectific
Opened_by
Edited_by
Closed_by

Exit Edit T-Card Browse Notes Prev Next Regs WSheet AddTask
WorkCtrl

- G-BAZX -

PARTS REQUISITIONS

Part No MS21076L3
Descr
Qty Reqd
Condition
Delivery
Task
IPC Ref
Requested by
Out Station

ENTER PART NUMBER

OK Edit Print Orders All Exit

- G-BAZX -

Job No 049254/HA Item10002 24/05/2012 Est. Man-hrs 0.00 Trade

PARTS REQUISITIONS

Part No MS21076L3 Buy Price 0.00
Descr ACHOR NUT
Qty Reqd 12
Condition NE
Delivery ROUTINE
Task 10002
IPC Ref N/A
Requested by JD
Out Station

Requisition Status
☒ Normal ☒ Normal
☐ Urgent ☐ Exchange
☐ Critical ☐ Loaner
☐ AOG ☐ Warranty

Notes

OK Exit

FILL OUT DETAILS

IPC Ref
Requested by
Out Station

N/A
JD

Create above Req

OK Cancel

Part No
Descr
Qty Reqd
Condition
Delivery
Task
IPC Ref
Requested by
Out Station

MS21076L3
ACHOR NUT
12
NE
ROUTINE
10002
N/A
JD

Requisition Status

CONFIRM
CREATED

Created above Req

OK

Part No
Descr
Qty Reqd
Condition
Delivery
Task
IPC Ref
Requested by
Out Station

SELECT

OK Edit Print Orders All Exit

PARTS REQUISITIONS

SELECT LINE(S) TO PRINT

Requisitions on Task No 10002

Print?	Date	Work Order	Task No	Acft	Cust	Reqd	Bal Qty	Qty Stck	Partno
Y	07/05/2013	049254/HA	10002	G-BAZX	DAS160	12	12	4	MS21076L3

Printer

Name: Brother MFC-620CN Printer

Properties

Status: Toner low; 0 documents waiting

Type: Brother MFC-620CN Printer

Where: BRN_71101F

CHANGE PRINTER THROUGH
NETWORK TO PRINT ON STORES
PRINTER

TO PRINT REQ
IN STORES

Zenner (Evaluation)
Printed 07/05/2013 @ 19:38:29

REQUISITION NOTE

Page 1

Aircraft G-BAZX

Job No. 049254/HA

PRINTED BY JD ON 07/05/2013 AT 19:38:29
THE FOLLOWING ITEMS ARE REQUIRED FOR THE ABOVE

ReqNo	Date	Task	Part Number	Description	Qty Requested	Balance Needed	Qty in Stck	Requested By
12351/REQS 07/05/2013 TaskNo 10002	10002	MS21076L3		ACHOR NUT	12	12	4	JD

TaskNo 10002