

MIN QTY REPORT

Zenner (Evaluation)
CAFAM64 System-Main Menu

MATERIALS **TECH SVCS** **FLT TIPS**

Inventory Control
Edit Issues/Recpts
Print Reports
Locate
Purchase Orders
Exclude
Display
Count
Inventory Control
Rec
Se
Is
Ra

Print Reports
Inventory
Purchase Orders
Below Minimum
Rec
Par
Sto

Outstation Code

Blank=Base
Enter '/' to total all stock together
(O/Stations ignored)

Exclude these Bins:
From To Blank=ALL (no exclusion)

RULES OF SEARCH for O/Station Code

1. Entering a slash "/" will total and group all the stock together regardless of O/Stations
2. Leaving the prompt <Blank> will only report on "Blank" i.e. your "Base"
3. Entering the O/Station will only print the Min Qty position at the O/Station selected

In addition you can elect to exclude from the count any specific range of bins, e.g. you may have chosen to hold your reserved stock in a bin G-XXXX where you are using the Aircraft Regn. Here you can specify "G-" to "G-" to exclude these

Enter '/' to total all stock together
(O/Stations ignored)

Exclude these Bins:
From To Blank=ALL (no exclusion)

SAMPLE REPORT

MINIMUM STOCK REPORT

Consumable Items - In-Sufficient on Order
/station=EDI Code=ALL

PART NUMBER	DESCRIPTION	Total	STOCK		ORDERED		REQS	MIN	MAX	REQD QTY		SUPPLIER
			This O/S	Alternat	This P/no	Alternat				This P/no	Incl Alt.	
N960-516	WASHER	68	28	0	0	0	0	50	0	-22	-22	