



COMPONENT CURRENT STATUS REPORT


1. Select:



2. Enter Aircraft & click OK



3. Respond [YES] to Components on next prompts



4. Select All Details or Just Summary



5. Report example

Zenner (Evaluation)
Printed 13/10/2018 @ 11:19:43

CURRENT STATUS SUMMARY
COMPONENTS
G-ABCD
TYPE CESSNA F406 S/No -5699

Page

Total Time: 554.0hrs, 635ldg, 635cyc, 0Fatg. - as at: 06/07/2009

| Part No. | Descr | Serial | Installed on | Next Due | | Remaining | | Scrap Life Remaining | Action | Positn | Sour |
|-----------|--------------|--------|--------------|----------|--------------|-----------|---------|----------------------|---------------|--------|-------|
| | | | | Hrs | Date Ldg/Cyc | Hrs | Ldg/Cyc | | | | |
| 9912480-1 | FWD | LK2666 | 06/05/07 | 10000.0 | | 9446.00 | | | REPLACE | RB | CESCC |
| | | | Freq: | 10000hrs | | | | | | | |
| 9912480-1 | FWD | LK2658 | 06/05/07 | 10000.0 | | 9446.00 | | | REPLACE | RT | CESCC |
| | | | Freq: | 10000hrs | | | | | | | |
| 9912480-2 | AFT ISOLATOR | LK1150 | 06/05/07 | 10000.0 | | 9446.00 | | | REPLACE | L | CESCC |
| | | | Freq: | 10000hrs | | | | | | | |
| 9912480-2 | AFT ISOLATOR | LK1205 | 06/05/07 | 10000.0 | | 9446.00 | | | REPLACE | R | CESCC |
| | | | Freq: | 10000hrs | | | | | | | |
| 9912491-5 | ACTUATOR | 0649 | 06/05/07 | | 33300LANDING | | 32665 | | OVERHAUL/REPL | NOSE | CESCC |
| | | | Freq: | | | | | | | | |