

## TASK DETAILS

Task Details entered and controlled from here:

Zenner (Evaluation)  
CAFAM64 System-Main Menu

Network: Y  
JD- 01/03/2012

MATERIALS TECH SVCS FLIGHT OPS **JOB CNTRL** BILLING UTILITIES CUSTOMENU EXIT

Time Card Entry  
Open/Edit Job No  
Print Reports  
Employee Details  
Search Job Detail  
**Task Details**  
Additional Programs

**CAFAM64**  
Aircraft Maintenance Program

**Task Details**

Edit Tasks Work Report Open Regs Cancel

WorkPack PDF

Enter the Job Number  
**Edit Tasks**

JOB NUMBER 049251/HA

OK Cancel

Will bring the Task Screen with self-explanatory buttons:

Search Job Detail  
Task Details  
Additional Programs

**CAFAM64**  
Aircraft Maintenance Program

Job No 049251/HA Item 10001 25/09/2009 [Est. M/hrs: 0.00, Labr: 0.00, Parts: 0.00]  
X-Ref Trade

Descr 100 Hr Check + annual Inspectio  
ATA

Rectific

Exit Edit Delete Browse Notes Prev Next Defect WSheet Add

## Adding a blank W/sheet

Job No 049251/HA Item 50005 | 01/03/2012 | [Est. M/hrs: 0.00, Labr: 0.00, Parts: 0.00]

X-Ref

Trade ☐

Descrpt  
ATA

Rectific

Dupl Insp ☐

OK Cancel

## Select Print Wsheet

Exit Edit Delete Browse Notes Prev Next Defect WSheet Add

## and select from the list

50003	N	T/p plane bearing worn
50004	N	U/C door slightly worn
50005	Y	

## /Prints the W/Sheet (including blank)

Zenner (Evaluation)  
CAFAM System  
01/03/2012



## WORKCARD G-ABCD



CESSNA 560XL S/No -5699

Hrs: 180.6 Ldg: 159 Cyc: 153

100 HR INSPECTION-ANNUAL					
RAISED BY		WORK ORDER	049251/HA		
EST. HRS		ITEM No	50005		
TASK DESCRIPTION	WORK CARRIED OUT / ACTION TAKEN		MECH	SIGN	

-end-